

5/019/0059
Outgoing

Paul Baker <paulbaker@utah.gov>

Task: 5644

Erosion at Leonard Murphy

1 message

Paul Baker <paulbaker@utah.gov>

Fri, Oct 11, 2013 at 1:20 PM

To: Raphael Cordray <craphaelc@gmail.com>

Cc: April Abate <APRILABATE@utah.gov>

Ms. Cordray--

On September 10, 2013, the Division of Oil, Gas and Mining received photos from you of erosion and breached berms at the Leonard Murphy mine operated by US Oil Sands. April Abate inspected the site on September 18, 2013, verifying the information we received from you. The operator has repaired the breaches as shown in photos they sent us and included in the attached inspection report.

With the additional rainfall received over the past few days, I will suggest that they re-inspect the berms to see how they held up. We may need to find a different sediment control method if this is a recurring problem.

Thank you for your concern.

—

Paul Baker

Minerals Program Manager

Utah Division of Oil, Gas and Mining

801-538-5261

M-W, F

**Insp-9182013.pdf**

6930K